



INSTITUT GRAĐEVINARSTVA HRVATSKE d.d.
CIVIL ENGINEERING INSTITUTE OF CROATIA

RRESHEN KALIMASH MOTORWAY PROJECT
Consultants Services for Supervision of Works

Office: Twin Towers 4/4, Bul. Deshmoret e Kombit, Tirana, Albania
tel + 355 4 280 431; fax + 385 4 280 432

Reps, 03 February 2009. Port. No. 231/2009

General Road Directorate

Rruga Sami Frasheri 33 Tirana
Albania

Attn. The Engineer Mr. Andy Toma

c.c. PIT Director Mr. Ylli Gjoni
c.c. PM Mr. Lionel Etherington

Bechtel – Enka Joint Venture

Blue Tower, 11th Floor / A3
Bul. Deshmoret e Kombit
Albania

Attn.: Mr. Mike Swinford
Mr. Ibrahim Karagaac

Subject: Rreshen to Kalimash Motorway Project- Supervision services
Non-Conformities in Produced Concrete, Component Concrete

Ref, IGH Letter Prot No 166/2008 dated October 6, 2008.

Dear Sirs,

We inform you that the case described in the Clause 7.5/ of the Contract/Rejection, due to the “found defect of the aggregate used in concrete works”.

Our statement is based on conclusion from the *Document No 25299-PET-KOQU-CTA-032-00001* received with *Document Transmittal Sheet No 25299 QAC-XMT-00120*. Part of this document have brought up a big concern regarding possible problems with aggregate used in concrete mixture in structures on Section 3 (tunnel, bridges and other structures).

We would like to apply the condition from our letter dated **October 6, 2008 Prot No 166/2008** not to certify concrete production for Section 3. We propose to omit concrete tunnel lining as precaution measures which shall stay until the Contractor ensure that all concrete works meet required quality.

We suggest to the Engineer to order from the Contractor to perform additional test which shall be recommended mutually by Designer, Supervisor and Contractor, using clause 7.4 from the Contract

Your action is very high appreciated and urgent.

With Compliments,

Ljupco Lamov

DPME

Mladen Jelacic

CRE / PM

